SHOP EQUIPMENT



High performance ignition coils that offer the lowest inductance for trouble free high RPM operation and the fastest rise and discharge time. The provided spark is in excess of 45,000 volts over the entire RPM range. Profire coils are black with single or dual high tension towers. Coil connectors and boots included. Available in 0.3 ohm, 0.6 ohm and 3.0 ohm. Sold each.

20-8425	Single lead	0.3 ohms	20-8	3411	Single lead	3.0 ohms
20-8409	Single lead	0.6 ohms			Dual lead	3.0 ohms
20-8412	Dual lead	0.6 ohms				

Note: DO NOT use **NOLOGY** Coils on point type ignitions or on the following motorcycles: Honda VFR, CB, CBX; Kawasaki ZX10, GPz, KZ1000J, Z1; Suzuki GSX-R (early oil cooled), GS; Yamaha-FJ, V-Max.

K&L CHARGE (SOURCE) COIL for ATV & OFFROAD

Sold each. Made in Italy.

Available for the following applications:



K&L HONDA ATV PULSER COIL

OEM replacement. Sold each. Made in Japan.



HONDA ATV	
20-3489 30300-HA0-033	
ATC125M	86-87
TRX125 Fourtrax 125	87-88
ATC200X	86-87
TR200 Fatcat	86-87
TRX200/D/SX Fourtrax	86-97
ATC250SX	85-87
ATC250ES Big-Red	86-87
TRX250TM/TE Fourtrax Recon	02-09
TRX250EX Sportrax 250	01-08
TRX250 Recon 250	85-01
TRX250X	87-92
TRX300 Fourtrax 300	88-00
TRX300EX Sportrax 300EX	93-08
TRX300X	2009
TRX300FW Fourtrax 300 4x4	88,90-00
TRX350 Fourtrax Foreman 4x4	86-87
TRX350D	87-89
TRX350FE/FM/TE/TM Fourtrax Rancher 4x4	00-06
FL400R Pilot	89-90
TRX400FW Fourtrax Foreman	95-03
TRX400FA/FGA Fourtrax Rancher	04-07
TRX450ES/FE/FM/S Fourtrax Foreman	98-04
TRX500FA/GA/PA Fourtrax Rubicon	01-09
TRX650FA/GA Fourtrax Rincon	03-05

89-90
89-90
96-04



Nology Hot Wires store coil energy until it can be released as an ultra-short, ultra-hot spark. Expect better horsepower and torque (2% to 5%), no fouled plugs, less backfires and a better starting engine. Each kit includes a 30" Hot Wire with grounding strap, 90 degree or straight spark plug cap, in-line wire connector and heat shrink tubing. Order one kit per cylinder.

20-8403 180° cap **20-8402** 90° cap



REPAIR KIT

Are the coil connectors on your motorcycle broken or simply wont stay clipped to the coil? This handy kit includes the terminals

and connectors necessary to repair a set of 4 damaged coil connectors. Kit also works on ATV and Watercraft models with stick coils.

20-8430 Coil Cap Connector Repair Kit

Kit contains: connectors (4), Terminals (10) and Terminal seals (10) Replacement sold in

34-0286 FWY-2F-B 2 Pin Female Coupler (pk/10)

34-9296 FRS-102 Terminal pin, Female (pk/50) **34-9297** FRS-103 Pin Seal (Black) (pk/50)

ACCEL SUPER COILS



20-6702, 20-6703

20-6701



Super Coils feature extremely high output, with racetrack proven performance on all motorcycles. Sold in single and two coil kits.

20-6701 Accel (140403-S) Single coil for Inductive Ignition (3.0 ohms) **20-6702** Accel (140403) 4 cyl. Kit for Inductive Ignition (3.0 ohms) **20-6703** Accel (140404) 4 cyl. Kit for CDI Ignition (1.2 ohms)

Note: Using the wrong coil may damage your ignition module. To determine ignition type, perform the following test:

- 1) Using a voltmeter or 12 volt test light, hook positive lead to positive post and negative to ground on one of the stock coils.
- 2) Turn on the ignition but do not engage the starter motor.
- 3) If there are 12 volts at the coil, the motorcycle has inductive type ignition. If there is no voltage at the coil, then the motorcycle has a capacitive discharge ignition (CDI) because the power goes to the control box first.